

DAIRY DIGESTERS

February 26, 2020



Photo by Ryan Song on Unsplash




Figure 2: Operating On-Farm Food Waste Co-Digestion Systems by State (2015)




On-farm manure comprises 70% or more of waste

Photo from dairymaster.com



Off-site waste (e.g., food processing waste, restaurant grease) up to 30% of biomass

Figure 4 – Biogas Generation Potential of Substrates



Source: Data derived from www.biogas-energy.com, © 2007 Biogas Energy, Inc., translated from: Basisdaten Biogas Deutschland, März 2005,; Fachagentur Nachwachsende Rohstoffe e.V.

MAINTAIN BALANCE

DIGESTERS \approx STOMACHS



cow manure



off-site feedstock







COMPLETE MIX DIGESTER



DVO'S MIXED PLUG-FLOW™



Digesters are designed by optimizing the retention time (typically between 22-28 days) to maximize CH₄ capture.



To preserve retention time, mixing occurs around the *axis of flow*. Waste slowly "corkscrews" its way through the digester.

<https://mrec.org/files/2016/06/2016.Dvorak.WhereAreWeTodayWithDigesters.pdf>



www.daritech.com/digesters.html









Biogas Production:
55%-70% methane
30%-45% carbon dioxide (CO₂)
Hydrogen sulfide (H₂S) in ppm





1,057 hp engine with 750 kWh generator



Average 527 kWh - power for 400+ homes

*In Washington State:
\$100 / MWh - decade ago
\$35 / MWh - now*

EMISSION COMPARISON

VOC, NO_x, PM, SO₂ [used for registration fees]

Examples of Registered Sources	Emissions (tons/yr)
Auto body shops - VOCs <ul style="list-style-type: none">Small to large (e.g., Maaco)	≤ 2
University - NO_x <ul style="list-style-type: none">WWU - Boilers, generators, gas station, wood shop, spray booths, solvents	9
Gas stations (largest) - VOCs <ul style="list-style-type: none">Safeway and Fred MeyersCostco	6-13 18-26
Wood products (mid-to-large) – PM₁₀ <ul style="list-style-type: none">Interfor Cedarprime, South Everson Lumber Co., SOCCO Forest Products, Lynden Door, Brooks Mfg., Mount Baker Products, Metrie Inc.	12-22
Anaerobic digesters (largest) – NO_x & VOC <ul style="list-style-type: none">FPE Renewables LLC, Edaleen Cow Power, Farm Power Rexville & Lynden	21-28




PROBLEMS

1. High H₂S concentrations
2. Timely engine testing
3. Flaring issues
4. Digester roof failures
5. Equipment leaks


1. H2S CONCENTRATIONS




Anytime H2S Limit 550 ppm
30-day rolling limit 350 ppm



BALANCE





UPSET




Concentration (ppm)	Symptoms/Effects
700-1000	Rapid unconsciousness, "knockdown" or immediate collapse within 1 to 2 breaths, breathing stops, death within minutes.
1000-2000	Nearly instant death

H₂S
SO₂



SO₂ - BIOGAS VS NATURAL GAS





Performance Tests for Nitrogen Oxides, Carbon Monoxide and Volatile Organic Compounds



2. TIMELY ENGINE TESTING

40 CFR § 60.4243(b)(2)(ii) – testing non-certified engines



Issue Date	Description/Notes
	1. Failure to perform required engine performance testing every 8,760 hours of 2. Failure to combust all digester gas in the engine generator or the flare. NW 3. Based on information provided by the facility during a follow-up visit on 8/ 4. Failure to report a breakdown or upset of the inoperative flare which allowe 5. Failure to keep process and/or air pollution control equipment in good con 6. Failure to maintain records of all offsite materials used as feed for the anaer 7. Failure to maintain a written log on a daily basis that included scf/day and s
08/26/2019	
11/01/2017	1. The test report documenting the May 25, 2017 source test was submitted to 2. The test report submitted to NWCAA on September 18, 2017 did not includ
04/27/2017	Failure to perform required engine performance testing every 8,760 hours of Failure to perform required engine performance testing every 8,760 hours of
07/22/2015	You are required to take the following action: Within 30 days from the receipt of this NOV, a complete source test plan mus




3.A. FLARING ISSUES

No spark-ignition during power outages



3.B. FLARING ISSUES

Permit applications indicated flaring $\leq 10\%$



33%	Total Gas Volume of Flare	108262019 CF
	Total Gas Volume of Engine	224813753 CF
	Total Gas Volume of Engine and Flare	333075772 CF



Permit Implications Regarding:

- Emissions
- Flare Design
- O&M
- Monitoring
- Record-keeping

3.C. FLARING ISSUES

Flare ignition failures during normal operation – flow, but no flare

Date	Time	Flow over 15 min	Avg. CFM	FlareTemp
7/27/2019	8:00:00	3570	238	84
7/27/2019	8:00:00	2598	173	80
7/27/2019	8:00:00	2970	198	84
7/27/2019	8:00:00	685	179	77
7/27/2019	8:00:00	76	165	78
7/27/2019	8:00:00	2855	190	80
7/27/2019	8:00:00	2158	144	79
7/27/2019	9:45:00	2609	174	80
7/27/2019	10:00:00	383	26	73
7/27/2019	10:15:00	206	14	76
7/27/2019	10:30:00	207	14	76


No Flare
Temp
18% of time

SCFM	Temp
197	1088
266	994
171	892
193	1277
203	766
278	1081
190	845
189	1310
180	1125
189	1259
183	1212



3.C. FLARING ISSUES

Flare ignition failure due to poor gas quality (e.g., an upset caused by freezing weather)



4. DIGESTER ROOF FAILURES



Farm Power Lynden (built 2010)
Lid collapse June 2019

- Result in alternate operations (i.e. run commercial natural gas)

Edaleen Cow Power (built 2012)
Lid collapse October 2019





Van Dyk-s Holsteins (built 2011)
Lid split July 2018

Google Earth

Imagery Date: 7/15/2018 48°54'51.01" N 122°24'37.32" W elev 73 ft eye alt 449 ft

5. EQUIPMENT LEAKS

- Leaking equipment







RESOLVED / TO BE RESOLVED

1. High H₂S concentrations
 - Generally under control during normal operation
2. Testing uncertified engines
 - Most conducted in timely manner
3. Flaring issues
 - No ignition during power outages
 - Battery back-up units have been installed
 - Flaring more than 10% represented in permit applications
 - Re-permitting – cap volume of biogas production
 - Flaring without combustion (high wind, low flow, spark failure, low CH₄)
 - Re-permitting – monitor and report flare temp and flow
4. Digester roof failures and upsets
 - Re-permitting - address the use of natural gas
5. Leaking equipment
 - Need further field evaluation to determine extent of leaks





NORTHWEST CLEAN AIR AGENCY

Matt Holmquist

matth@nwcleanairwa.gov

360.419.6840